

FIG. 1




FIG. 2





FIG. 3






FIG. 4




FIG. 6A




FIG. 6B




FIG. 7A




FIG. 7B







FIG. 8A

INCIDENT
DIRECTION
OF LASER
BEAM



SUB-SCANNING
DIRECTION

INCIDENT
DIRECTION
OF LASER
BEAM



SUB-SCANNING
DIRECTION

FIG. 8B

FIG. 8C


FIG. 8D

INCIDENT
DIRECTION
OF LASER
BEAM



SUB-SCANNING
DIRECTION

INCIDENT
DIRECTION
OF LASER
BEAM



SUB-SCANNING
DIRECTION

FIG. 9A




FIG. 9E




FIG. 9B MASK REMOVAL




FIG. 9F MASK REMOVAL




FIG. 9C ETCHING




FIG. 9G




FIG. 9D

MASK REMOVAL





FIG. 9H

MASK REMOVAL






FIG. 11B




FIG. 11C




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14
PRIOR ART

